

Commercial cooling Tower Case Study - 90 Day Evaluation

Case study updated on April 26, 2013

Installer: Nano Tek-On - HydroFLOW Master Distributor in Hawaii.

Customer: Central Pacific Plaza Location: Honolulu, Hawai - USA

Application: Two 300 ton cells and one 75 ton cell - One 300 ton cell operates during the day, one 300 ton cell is on

standby and the 75 ton cells operates during the night

Unit: HydroFLOW 14" Custom on a 12.78" Outer Diameter Cast Iron Pipe

Goal: Keep biological growth, scale accumulation and corrosion rate under control while using minimal

amounts of chemicals

Timeframe: Trial began on January 22, 2013 and ended on April 22, 2013

Evaluation Protocol:

Weeks 1-2: No chemical reduction. Biological water tests to be compared to baseline data after 15 days. Scale and bio accumulation to be compared to baseline pictures.

- Weeks 3-5: Scale/corrosion inhibitors and biocide to be reduced to 75% (25% reduction). Biological water tests to be compared to baseline results after 5 weeks. Scale and bio accumulation to be compared to baseline pictures.
- Weeks 6-9: Scale/corrosion inhibitors and biocide to be reduced to 50%. Biological water tests to be compared to baseline results after 9 weeks. Scale and bio accumulation to be compared to baseline pictures.
- Weeks 10-12: Customer to decide if scale/corrosion inhibitor and biocide can be reduced to 25% (75% reduction). Biological water tests to be compared to baseline results after 12 weeks. Scale and bio accumulation to be compared to baseline pictures.


Cooling Tower Cells







Installation Location - After Sump Pumps (Before the Chillers)





Results after 90 days

- Lime scale and corrosion buildup inside the cooling tower and chillers remained under control even though antiscalant and anti-corrosive chemicals were discontinued
- Biocide chemical was reduced by 85% and bacteria levels reduced from 100,000 CFU to 1,000 CFU
- Blow-down reduced by 50%
- Conductivity remained stable at 1245 $^{\sim}$ 1295 Micro Siemens

Before and After Pictures

Before After





Lime scale and corrosion buildup remained under control even though anti-scalant and anti-corrosive chemicals were discontinued



[Dip slides were used to monitor biological count]

Before After



Biocide chemical was reduced by 85% and bacteria levels reduced from 100,000 CFU to 1,000 CFU



Return On Investment - Under 4 months

Cooling Tower Descr	iption			Hydro FLOW	/ Solution				
Tower Type	Open	Remaining Life, yrs	20	Hydro FLOW Model		P14"	Installed I	Price	\$35,691
Unscheduled Downtime to Replace Tower, hrs 48			Payback Period		Months			Months	
Est Tower Replacement Cost (incl. installation), \$ \$200,000			Cash Flow Breakeven		3.8	Simple Pay	back	3.5	
Tower Tonnage 300			Financial Re	turn (ROI)	%			%	
				Internal Rat	e of Return	317%	Simple Re	turn	340%
Equipment Replacen	Total Ownership Cost Savings								
Piping, yrs	20.0	Tubes or Fills, yrs	20.0		Financial	l Life Cycle Period for Analysis, yrs			30
Cost Incl Labor, \$	\$15,000	Cost Incl Labor, \$	\$15,000			Current	Hydro FLO	W	Savings
Offline, hrs	48	Offline, hrs	48	Capital Equipment		230,000	\$ 65	,691	164,309
					Electricity \$	5,409,378	\$ 3,516	,096	1,893,282
System Parameters					Water \$	2,576,424	\$ 1,288	,212	1,288,212
Annual Hours of Operation, hrs (1 yr = 8,760) 8,7			8,760		Chemicals \$	240,000	\$ 84	,000	156,000
Revenue Lost When Tower is Offline, \$/hr			\$1,000	М	aintenance \$	150,000	\$ 97	,500	52,500
					Downtime \$	144,000	\$ 96	,000	48,000
Operating Costs					Total \$	8,749,802	\$ 5,147,	499	3,602,303
No. of Fan Motors	3	Fan Motor HP	20	Cost of Capital		10%	NPV of Savin	gs, \$ \$	1,073,512
No. of Sump Pumps	1	Pump HP	20]		Average	Annual Savin	gs, \$ \$	121,266
	Ele	ectricity Cost (\$/kWh)	\$0.34						
Cycles	2	Bleed (Gal./Min.)	9.00	Cumulative Cost Difference Over					
Potable Water Cost (\$/ccf) \$2.81				HydroFLOW Life					
Sewage Cost (\$/ccf) \$10.77						riyaroi Lo	VV LIIC		
10% Side Stream Filtration (50 Micron) No			10,000,000						
				9,000,000					
Chemical Costs				8,000,000					$\overline{}$
Annual Chemical Cost, \$ \$8,000				7,000,000					
				6,000,000					
Maintenance Costs				5,000,000					
Annual Tower System Maintenance Cost, \$ \$5,000				4,000,000					-
	'DD			3,000,000					
Company Name:	PP	Phone:		2,000,000					
Address		amail.		1,000,000					
Address:		email:		0					
Application: T		0 5	10	15	20	25			
rippiitation.	Current Cumulative Cost HydroFLOW Cumulative Cost								

Referral Information

Please contact Harald Von Sydow, Owner of Nano Tek-On, in order to receive the customer's contact information.

Phone: (808) 395-2996

Email: nanotekhi@hawaii.rr.com

Website: www.nanotekhi.com